L1™ Model II power stand firmware v1.1 Release Notes

We are also, including an update to the L1 Model II power stand firmware version 1.1. This new firmware addresses the following issues:

Bug Fixes:

1.) Fixes a bug where some power outages could cause the L1 model II to hang. This is related to the problems reported on the message board where some users have experienced a loss of audio sometimes accompanied by a blank blue T1 LCD screen.

Enhancements:

1.) We've also made some changes to the fan behavior to make it less noticeable.