

L1® Model II System Firmware Update – READ ME

PLEASE REVIEW THIS DOCUMENT BEFORE UPDATING YOUR L1® MODEL II SYSTEM

1. Please note you must perform the update via your T1 ToneMatch® audio engine. You CANNOT plug your computer directly into the L1 Model II ToneMatch Port.
2. There are two files included in this folder that must be updated in order for your L1 Model II to be fully compatible with the B2 Bass module.
 - a. *Bose_L1MII_PSII_FIRMWARE_v14.bos* – YOU MUST UPDATE THIS FILE FIRST
 - b. *Bose_L1MII_EQ_V1.04.bos*
3. Update the **PSII Firmware**. Use the following file: *Bose_L1MII_PSII_FIRMWARE_v14.bos*. This could take up to 20 minutes.

PS II Firmware

PS II Firmware:

Update

When you are using an L1™ Model II power stand to provide power to the T1 ToneMatch™ audio engine the current Firmware version of the power stand is displayed on the application screen.

4. Update the **PS II system EQ**. Use the following file: *Bose_L1MII_EQ_V1.04.bos*. This should take less than a minute.

PS II System EQ

PS II System EQ:

Update

When you are using an L1™ Model II power stand to provide power to the T1 ToneMatch™ audio engine the current version of the power stands EQ settings are displayed on the application screen. This version is part of the power stands firmware version.

5. Power cycle the power stand.